

—




FIGURE 2




FIGURE 3

200




FIGURE 4

200

210

206

Drawing Wizard

Drawing Mode

☒ Create
☒ Edit

Create Drawing

☒ Cycle All
☒ View Placement
☒ Holes
☒ Slots
☒ Welds
☒ Item Balloons
☒ Marking Label
☒ Dimensions

Edit Drawing

☒ Cycle Item Balloon to Alt Solid
☒ Cycle callout to Alt View
☒ Remove Extra callouts

230

232

234

243

240

242

204

Figure 5

6/8

250



260

262

264

270

272

274

316

314

Weld Builder

Mode

- ☒ Add Weld
- ☒ Delete Weld
- ☒ Display Welds

Add Weld

- ☒ Corner
- ☒ Butt
- ☒ Fillet

Delete Weld

- ☒ Selected
- ☒ All

OK **Back** **Cancel**

252

254

256

FIGURE 6




Figure 7




FIGURE 8